

ELEVATOR STAKEHOLDERS MEETING

Tuesday – May 18, 2010 – 9:00 A.M.

**Division of Building Safety
1090 E Watertower Dr, Meridian, Idaho**

NOTE: The following report is not intended to be a verbatim transcript of the discussions at the meeting, but is intended to record the significant features of those discussions.

The meeting was called to order by Al Caine Industrial Safety Program Manager at 9:05 a.m.

Al Caine introduced himself and then introduced Gary Barnes, a Division of Building Safety – Industrial Safety Inspector

◆ Presentation

Significant Changes of the 2007 editions of ASME Elevator Safety Codes that may impact **NEW** elevator installations (Please see PowerPoint Presentation)

◆ Questions

MCP – Maintenance Control Plans: Where is the state going to stand on these?

Answer: At this time the state inspector will require the MCP be made available to them at the time of inspection. We would like to see a minimum of two years worth of maintenance records.

What about sump pumps and oil/water separators on existing elevators?

Answer: A17.3-1.2 does not require a sump pump or oil/water separator to be added to an existing elevator. We will write up on our reports an oil/water separator if it is tied into the sewer line because that is specifically prohibited. All other requirements for the oil/water separator fall under the plumbing code for that jurisdiction.

Meeting Closed at 10:25 a.m.